

Bendo Bridge - NY-53-04

DeBruce, NY - Sullivan County




Photo of Bendo Bridge



Bendo Bridge Portal

Bridge Statistics

Region: *Catskills - Route 17 / I86*

County: *Sullivan*



Town: *Rockland*

Locality: *Debruce*


Owner: *Unknown*

Bridge Carries: *Conklin Road*

Bridge Crosses: *Willowamoc Creek*

Bridge Traffic: *Vehicular*

Truss Type: *Town Lattice*



Year Built: *1860*

Builder: *John Davidson*

Moved By: *Joseph Sherwood (1913)*

Length: 48'-0"

Structure Characteristics: *Width: Unknown*

Lanes: 1

Posted Load: *None*

Posted Vertical Clearance: *None*

World Guide No.: *32-53-04*

National Register of Historic Places

Date: *Does not qualify*

Description

The Bendo bridge is on Conklin Road and crossed the Willowemoc Creek. This is a 48 foot town lattice truss, built in 1860. The bridge is next to the Covered Bridge Campground which was not yet open for the season during our visit in April, 1998. The bridge was cut in half and moved to this location in 1913. This bridge was originally located in Livingston Manor.

Photography

Easy to photograph portal since the bridge traffic is light. A path leads down to the creek with a nice location for a side photo.

Parking

Parking available after crossing bridge.

Additional Information

Covered Bridge Campsite

Truss / Arch

Town Lattice Truss

No photo available

Location Map



Location

5.6 miles east of NY17 on CR82 (Exit 96) to DeBruce, then 1.8 miles right on Willowemoc Road and 0.4 miles right on Conklin Hill Rd to Covered Bridge Campsites. The bridge is located in the town of Rockland in Sullivan County.



[Return to New York Covered Bridges](#)