

Grahamsville Bridge NY-53-B

Grahamsville, NY - Sullivan County



Photo of Grahamsville Bridge



Photo of Grahamsville Bridge Portal



Photo of Grahamsville Bridge during flooding in April 2005



Photo of Grahamsville Bridge Portal during flooding in April 2005

Bridge Statistics

Region: *Catskills*

County: *Sullivan*



Town: *Neversink*

Locality: *Grahamsville*

Position - Lat: *N 41 51.270*

Lon: *W 74 33.315*

Type: *Other*

Owner: *Unknown*

Bridge Carries: *River Road*

Bridge Crosses: *Chestnut Creek*

Bridge Traffic: *Vehicular*

Superstructure Type: *Steel Stringer*

Year Built: *1976*

Builder: *Unknown*

Length: 40'-0"

Structure Characteristics: *Width: Unknown*

Lanes: 1

Posted Load: *None*

Posted Vertical Clearance: *None*

World Guide No.: *32-53-B*

National Register of Historic Places

Date: *Not Applicable*

Description

The Grahamsville or Chestnut Creek covered bridge is a steel stringer structure with the look of a town lattice truss. It crosses Chestnut Creek in Grahamsville, a short distance from the Halls Mills Bridge.

Photography

Easy from road, difficult side views.

Parking

On shoulder near bridge.

Truss / Arch




Photo of Grahamsville Bridge Truss

Steel Stringer Superstructure

No photo available

Location Map



Location
West of village of Grahamsville off Rt55.



[Return to New York Covered Bridges](#)